

# AMCO NEWS

Vol. XVIII No. 2

Adams-Millis Corporation

February, 1960

## *CHECK LIST USED FOR QUALITY*



The Quality Control Committee of Plant #4 checks the elastic tops of stretch hose. Members of the Committee selected from each department are, left to right: Donald Stanley, Lilly Flynt, Dorothy McGee, Edna Morton, Betty Dull and Leonard Taylor.

The check list to guide the Quality Control Committee is as follows:

**KNITTING** - Check at machines for holes, misplaits, bad sizing and oil spots, or any other defect.

**LOOPING** - Check loopers for looper holes, brushing and oil spots.

**INSPECTING** - Check on clippers for clipper holes, clipping too short or

leaving too long and turning out tops.

**DYE HOUSE** - Check on shades in stretch goods, mildew in other styles.

**BOARDING** - Check patterns, heel and toe for bad boarding.

**BERRY-PAK** - Check for straightness, holes, misplaiting on Berry-Pak.

Check clippers for leaving strings or cutting holes.

**PAIRING** - Check pairing, shades, holes, misplaiting or any other defect which might cause an off-grade.

**FINISHING** - Check transfer for centering and straightness, also riders.

Check machines for transfers, riders and bands. Check folders for neatness.