



The unique formulation of proven elements, properly ground and mixed in huge vats in the mixing room are piped to the coating machine without coming in contact with air.

Benny Rich checks and records coating mix temperature and the pressure and temperature of the coating room for quality control purposes.



Before entering the coating room, Arlo Hoover dons a white coat and changes to shoes worn only in the coating room. These measures are taken to prevent contaminating the coating material.

Arlo Hoover cleans each roll of mylar base with vacuum cleaner to insure there is no lint nor dust present on the film before the coating is applied. Purity of elements is essential to the high fidelity of top quality tape.

