



Donald Stanley, representing the knitting department on the Quality Control Committee, found "by feel" a sock which he thought to be too large for the size being knitted. The sizing board proved Stanley to be correct. This



Tighten Stitch

called for tightening the stitch, being done in the above picture. Kenneth Idol is the fixer adjusting the machine.



Cause Of Streak

London Kidd, fixer, and John Boyer, knitter, look for the cause of a bad streak in a stocking. A defective sinker was located and replaced.



Goods Returned To Knitting

At this point, Dorothy Mabe, working with the regular Quality Control Department, brought some hose with bad plaiting from the pairing department to the knitting department to report to Ralph Wilson. This is part of the regular Quality Control procedure which functions constantly. Any work needing correction in any department at any time is immediately reported by the supervisor of the department in which it is found to the supervisor of the department in which the corrective measures are to be taken.



Seaming Quality Good

Helen Wilson, standing, checked

(Continued next page)